SAFETY DATA SHEET SUPERIOR No. 3033-87

DATE REVISED: August 6, 2018

SECTION 1 -- IDENTIFICATION

Product Name/Part number: Superior No. 3033-87

Recommended use:Tin-Silver Solder PasteManufacturer:Superior Flux & Mfg. Co.6615 Parkland BlvdCleveland OH, 44139

Emergency Contact: CHEMTREC Emergency Phone: 1-800-424-9300 For other info: (440) 349-3000

SECTION 2 - HAZARD(S) IDENTIFICATION

Classification of the substance or mixture

GHS Classification in accordance with OSHA HCS (29 CFR 1910)

Acute toxicity, Oral (Category 4)	H302
Aspiration toxicant (Category 1)	H304
Serious eye damage (Category 1)	H318
Acute aquatic toxicity (Category 1)	H400
Chronic aquatic toxicity (Category 1)	H410

GHS Label Elements, including precautionary statements Pictogram(s):



Signal Word: Danger

Hazard Statement(s)

- H304 May be fatal if swallowed and enters airways
- H318 Causes serious eye damage
- **H400 Very toxic to aquatic life
- H410 Very toxic to aquatic life with long lasting effects

**May be omitted from label due to presence of stricter or more specific hazard statement.

Precautionary statement(s)

- P264 Wash skin thoroughly after handling
- P270 Do not eat, drink or smoke when using this product.
- P273 Avoid release to the environment
- P280 Wear protective gloves, eye protection, protective clothing and face protection
- P301+P310 IF SWALLOWED: Immediately call a POISON CENTER or doctor
- P303+P361+P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower
- P305+P351+P338+P310 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER/doctor.
- P363 Wash contaminated clothing before reuse
- P391 Collect spillage
- P403 Store in a well-ventilated place.
- P501 Dispose of contents and/or container to an approved waste disposal plant.

Hazards not otherwise classified or not covered by GHS: None

SECTION 3 – COMPOSITION INFORMATION

Components	CAS Number	%
Tin	7440-31-5	82-84
Silver	7440-22-4	3-4
Polypropylene glycol	25322-69-4	<5
Isoparaffinic hydrocarbon	64742-46-7	<2
Pentyl acetate	628-63-7	<2
Hydroxybenzoic acid	69-72-7	<1
Carboxylic acid	98-98-6	<1

SECTION 4 – FIRST AID MEASURES

Description of first aid measures

General advice: Show this safety data sheet to the doctor in attendance. Move out of dangerous area.

Inhalation: Remove to fresh air. If not breathing, give artificial respiration or oxygen by trained personnel. Seek immediate medical attention

- **Eyes:** Flush with water for at least 15 minutes to remove irritant. Remove contact lenses, if present and easy to do. Continue rinsing. Seek medical attention if irritation persists.
- **Skin:** Remove contaminated clothing. Wash affected area with soap and water. Wash clothing before reuse. If irritation persists, obtain medical attention.
- **Ingestion:** If patient is conscious, ONLY induce vomiting as directed by trained personnel. NEVER give anything by mouth to an unconscious person. Seek medical attention immediately.

SECTION 5 – FIREFIGHTING MEASURES

Suitable Extinguishing Media: Use extinguishers appropriate for the surrounding fire conditions. Advice for firefighters: Use NIOSH/MSHA – approved self-contained breathing apparatus and full protective clothing if involved in fire.

Further information DO NOT USE WATER ON MOLTEN METAL. LARGE FIRES MAY BE FLOODED WITH WATER FROM A DISTANCE.

SECTION 6 - ACCIDENTAL RELEASE MEASURES

- **Personal Precautions and Equipment and emergency procedures:** Use personal protective equipment. Ensure adequate ventilation. Evacuate personnel to safe areas. *See section 8 for personal protection.*
- Methods and materials for containment and cleaning up Contain spill. If molten, cool to allow metal to solidify. If a solid metal, wear gloves, pick up and return to process. Dispose of alloy following all Federal, State, and local regulations. In the EU refer to the Special Waste Regulations. Metal may have reclaim value.

For disposal, see section 13.

SECTION 7 - HANDLING AND STORAGE

Precautions for safe handling: Further processing of solid materials may result in the formation of combustible dusts. The potential for combustible dust formation should be taken into consideration before additional processing occurs. Only dry metals should be added to molten bath. If working with molten metals, or exposed to fume or dust, use appropriate personal protective equipment.

!!! WET OR MOIST INGOT(S) <u>WILL</u> PRESENT AN EXPLOSION HAZARD WHEN

SUBMERGED IN MOLTEN SOLDER. AVOID FIRE/EXPLOSION RISKS – ALWAYS

PREHEAT INGOT BEFORE CHARGING INTO FURNACE. !!!

For precautions, see section 2.

Conditions for safe storage, including any incompatibilities Store product in a cool, dry area away from incompatible materials.

For full precaution statements see Section 2

SECTION 8 – EXPOSURE CONTROLS / PERSONAL PROTECTION

OSHA Permissible Exposure Limit (PEL):	1 mg/m ³
ACGIH Threshold Limit Value (TLV):	1 mg/m ³

- **General Precautions:** Handle in accordance with good industrial hygiene and safety practice. Wash hands before breaks and at the end of the workday.
- **Engineering Controls:** Use local exhaust ventilation to maintain air concentrations of dust, vapors and fumes below occupational exposure standards.
- **Respiratory Protection:** Where risk assessment shows air-purifying respirators are appropriate, use an authority approved or compliant marked air-purifying respirator with a fume/dust chemical cartridge is recommended under circumstances where airborne concentrations are expected to be elevated. Use respirators and components tested an approved under appropriate government standards such as NIOSH (USA) or CEN (EU).

Protective Gloves: Handle with leather or vinyl gloves

- **Eye Protection:** Chemical safety glasses or goggles, and face shield with molten metal. Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (USA) or EN 166 (EU)
- **Body Protection:** Impervious clothing and leather or vinyl gloves. Heat resistant gloves if handling hot metal. Safety boots. Personal protective equipment is recommended when working with molten metal to avoid burns.
- **Control of environmental exposure:** Prevent further leakage or spillage if safe to do so. Do not let product enter drains.

If used in solution, or mixed with other substances, and under conditions which differ from EN 374, contact the supplier of the CE approved gloves. This recommendation is advisory only and must be evaluated by an industrial hygienist and safety officer familiar with the specific situation of anticipated use by our customers. It should not be construed as offering an approval for any specific use scenario.

SECTION 9 - PHYSICAL AND CHEMICAL CHARACTERISTICS

- Appearance Odor **Odor threshold** pН Melting point/Freezing point Initial boiling point and boiling range **Flash point Evaporation rate** Flammability (Solid, gas) Upper flammability or explosive limits Lower flammability or explosive limits Vapor pressure Vapor density **Relative density (Water = 1)** Solubility(ies) Partition coefficient: n-octanol/water **Auto-ignition temperature Decomposition temperature** Viscosity
- Silver grey paste Slight No data available No data available No data available No data available Not applicable No data available No data available Upper explosion limit: Not applicable Lower explosion limit: Not applicable No data available No data available No data available Insoluble in water No data available No data available No data available Not applicable

SECTION 10 - STABILITY AND REACTIVITY

Reactivity: No data available

Stability: Product is stable under recommended storage conditions
Possibility of hazardous reactions: No data available
Conditions to Avoid: Excessive heat, exposure to moisture
Incompatible Material: Avoid contact with mineral acids.
Hazardous Decomposition Products Harmful metal oxide fumes may form at elevated temperatures.

In the event of fire: See Section 5

SECTION 11 - TOXICOLOGICAL INFORMATION

Carcinogenicity National Toxicity Program (NTP): No Occupational Safety & Health Administration (OSHA): No U.N. International Agency for Research on Cancer (IARC): No LD50: Not established LC50: Not established Other: None

SECTION 12 - ECOLOGICAL INFORMATION

Toxicity Persistence and degradability Bioaccumulative potential Mobility in soil Other adverse effects No data available No data available No data available No data available

Avoid release to environment

An environmental hazard cannot be excluded in the event of unprofessional handling or disposal.

SECTION 13 - DISPOSAL CONSIDERATIONS

Waste treatment methods

Product Scrap metal alloy usually has value. Contact a commercial reclaimer for recycling. Otherwise, dispose of in accordance with local through federal environmental regulations. Contact a licensed professional waste disposal service to dispose of this material.

Metal may have reclaim value. Contaminated packaging Dispose of as unused product.

SECTION 14- TRANSPORTATION

D.O.T. (USA) Not regulated

SECTION 15 - REGULATORY INFORMATION

SARA 302 Components No Chemicals in this material are subject to the reporting requirement of SARA Title III, Section 302.

SARA 313 Components No

No chemicals in this material are subject to the reporting

requirement of SARA Title III, Section 313.

SARA 311/312 Hazards Hazardous to the environment, Acute health hazard

California Prop. 65 Components

This product does not contain any chemicals known to State of California to cause cancer, birth defects, or any other reproductive harm.

SECTION 16 - OTHER INFORMATION

Further information:

Judgments as to the suitability of information herein or the purchaser's purposes are necessarily the purchaser's responsibility. The above information does not represent any guarantee of the properties of the product. It is believed to be correct, but does not purport to be all inclusive and should be used only as a guide. Reasonable care has been taken in the preparation of this material, and is based on the present state of our knowledge.

Superior Flux & Mfg. Co. shall not be held liable for any damage resulting from handling or from contact with the above product. There are *NO WARRANTIES, NO REPRESENTATIONS AND NO RESPONSIBILITY AS TO THE ACCURACY OR THE SUITABILITY OF THIS INFORMATION FOR ANY PURCHASER'S USE OR FOR ANY CONSEQUENCE TO USE.*

Preparation information Superior Flux & Mfg. Co. 440-349-3000